

## SF50 Vision Jet - Line Maintenance Facility Service Bulletins Available at First Wing Jet Center

- SB5X-21-02: A/C Compressor Bolts Inspections
- SB5X-21-03: Air Conditioner Compressor Electrical Power Input Ports Inspection
- SB5X-21-04: Ram Air Duct Security
- SB5X-24-02: CAPS Shelf Ground
- SB5X-25-02R2: Crew Seat Track Guides
- SB5X-25-05: Removal of Passenger Seat Locking Plates
- SB5X-25-08: Inspection of Seatbacks
- SB5X-27-03: #6 Pitch Trim Pulley Bracket
- SB5X-27-04R1: Pitch Trim Hinge Lubrication
- SB5X-27-05: Pitch Trim Chain Lubrication
- SB5X-28-02: Fuel Calibration
- SB5X-28-03: Fuel Control Valve
- SB5X-30-02: Radome IPS Cable Routing
- SB5X-30-03: Radome TKS Shanked Bolts
- SB5X-31-02: Circuit Breaker Panel Cable Restraints
- SB5X-31-03: RDM Installation
- SB5X-32-01: Nose Landing Gear Axle Replacement
- SB5X-32-02R1: Brake Line Marking
- SB5X-32-05R1: Nose Structure Hardware Seal
- SB5X-33-01: Wire Harness Routing
- SB5X-42-01: CMC Software Installation
- SB5X-44-02: IFE Display Harness Support
- SB5X-52-03: Egress Window Seal Inspection
- SB5X-52-04: Baggage Door Water Management
- SB5X-52-05: Upper Gas Strut Replacement
- SB5X-52-06: Cabin Door Hardware Inspection
- SB5X-52-07: Passenger Door Pull Strap Magnet
- SB5X-53-03: Ram Air Duct Repair
- SB5X-53-06R1: Cabin Water Discharge
- SB5X-53-07: Empennage Bay Access Panel Hardware
- SB5X-53-08: H/W missing from Aft B/H
- SB5X-53-09: Firewall Hardware Sealant Application
- SB5X-55-07: Yaw Damper Drain Holes
- SB5X-57-05: Wing Skin Drain Holes
- SB5X-90-07: CAPS Cover Tape Inspections
- SB5X-91-02: Aft Wire Harness Routing
- SB5X-23-xx: Cabin Speaker Volume Adjustment
- SB5X-23-02: GDL 88 978 MHz Transmission
- SB5X-25-07: Inspection of Optional XC Seat Seatbelt Reels
- SB5X-28-04: Ejector Fuel Pump Assembly Inspection
- SB5X-28-13: Electric Fuel Pump Replacement
- SB5X-31-04: RDM (Recoverable Data Module) Inspection
- SB5X-36-01: Temperature Control Valve Assy Replacement
- SB5X-52-06: Door Mushroom Shanked Bolts
- SB5X-52-08: Baggage Door Water Ingress Prevention
- SB5X-74-01: Ignition Panel Installation
- SB5X-80-01: RH NACA Duct for Starter/Generator (GEN 1)